



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
January 6, 2010

Reviewed: PRB

Mine Name: Georgia Pacific Gypsum Quarry	Permit Number: M/041/0009
Operator Name: Georgia Pacific Corp.	Inspection Date: 6/22 and 8/26/2009
Inspector(s): Lynn Kunzler, Wayne Western	Time: 10:00 am
Other Participants: Bill Barger, Tom Brooks	Mine Status: undergoing reclamation

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

At request of operator, to inspect site of the 'Bump Blast'

Inspection Summary:

The operator has completed the bump blast on the northern half of the North Quarry as previously approved. Success of this experimental practice was favorable and the operator was given the OK to proceed with the rest of the North Quarry. After the bump blast is completed, there will be some regrading required to complete the reclamation of this site

A follow-up visit by Lynn Kunzler on August 26, 2009 found that most of the area had been regraded. There was still some areas that needed work, and the operator had equipment on site to take care of this. We also discussed seeding the site this fall. The operator was assured that it was acceptable to collect seed from the site to use. We then looked at other areas that the operator intends to begin reclamation on this year.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Aside from the reclamation work, there was no other activity at this site. The site appeared stable and was relatively free of garbage and debris.
Continue to monitor this site when in the area.

Inspector's Signature _____

cc: Tom Brooks (operator) TCBrooks@Gapac.com
O:\M041-Sevier\M0410009-GeorgiaPacific\inspections\Insp-06222009.doc